




DESCRIPTION

This document illustrates how to select the proper blower motor assembly for Model 695 Series warmers.

NOTES


Motors are not retrofittable.

Model 695 / 695B




0017207SK

Model 695C



0021012




0018631

0018632

0022309

0017230 (x8)

Model 695D



0022309