




DESCRIPTION

This document illustrates how to select the proper blower motor assembly for Model 695 Series warmers.

NOTES


Motors are not retrofittable.

Model 695 / 695B




0017207SK

Model 695C



0021012




0018631

0018632

0022309

0017230 (x8)

Model 695D



0022309

NOTE: Older unit may be equipped with motor like image to right with fan. Newer motors no longer require fan blade per UL.

Both motor styles are retrofittable to each other.

If only small fan blade required:
#0017331

